

Vehicle Details

Make: HYUNDAI

Model: ILOAD

Rego:

Year: 2014

Odometer:

VIN: Kmfwbx7kmeu633901

Engine No:

VEHICLE PRE-PURCHASE INSPECTION REPORT



Date: 4/7/2025

Job No: 19836

Customer Name: BAZAIN, CLEMENT

Address: 591 Carlisle Ave


















Minchinbury NSW 2770

ROADWORTHY & PRE-PURCHASE
INSPECTIONS

1300 191 981

Detail Inspection Report



INTERIOR					
CATEGORY	GOOD	FAIR	REPAIR	N/A*	NC*
Seats					
Seat Belts					
Other Trims					
Radio					
Rear Window Demister					
Air Conditioning					
Heater Demister					
Washer / Wipers					
Horn					
Doors, Locks & Hinges					
Window Operation					
Warning Lights & Gauges / Dash					
All Lights					
Other					

COMMENTS

Passenger side (left hand) sliding door does not lock or unlock via central locking (remote), needs to be manually unlocked and locked










Aftermarket head unit (radio) fitted

Some trim scuffs and missing reflector on inside of door

Detail Inspection Report



EXTERIOR

					
CATEGORY	GOOD	FAIR	REPAIR	N/A*	NC*
Rust					
Body Repairs					
Glass & Mirrors					
Sunroof, Aerial or Convertible					
Frames and Members					
Under Body Parts					
Front Suspension					
Rear Suspension					
Steering Components					
Transmission					
Exhaust					
Differential					
Drive Shaft					
Other					

COMMENTS

















Some dings found on some panels,

Some damage on passenger side sliding door and rear quarter panel (refer to photos) appears to have some touch up paint on it

Small chips in left tail light

Detail Inspection Report



ENGINE BAY						
CATEGORY		GOOD	FAIR	REPAIR	N/A*	NC*
Noise						
Fluid Level						
Fluid Leaks						
Mountings						
Hoses / Pipes						
Water Pump / Fan						
Ignition System						
Fuel System						
Battery						
Radiator / Cap						
Drive Belt / Pulleys						
Brake Booster						
Master Cylinder / ABS						
Other						

COMMENTS

Engine bay very clean as detailed, hard to detect if there is any oil leaks

Performed tk combustion leak test, appears to be ok at time of inspection (refer to image)

Radiator cap has black substance on it, recommend replacing radiator cap (refer to image)

Detail Inspection Report



TYRES, WHEELS & BRAKES

					
CATEGORY	GOOD	FAIR	REPAIR	N/A*	NC*
Tyres					
Wheel Rims					
Spare Tyre / Rim					
Brake Hose Callipers / Pipes					
Brake Pads					
Brake Discs					
Brake Linings					
Wheel Cyclinders					
Brake & Drums					
Park Brake					
Wheel Bearings					
Other					



















COMMENTS

Appear to be all ok at time of inspection

Some scuffs on wheels

Detail Inspection Report



ROAD TEST					
CATEGORY	GOOD	FAIR	REPAIR	N/A*	NC*
Ease of Starting Idle					
Engine Noise					
Engine Performance					
Exhaust Smoke / Emissions					
Gearbox (Auto / Manual)					
Differential					
Steering / Suspension					
Brake Operation					
Speedo					
Cruise Control					
4WD					
Camshaft / Drive Belt					
Logbook/Service					
Other					

COMMENTS

Car run smoothly, however at times coming to a stop, idle was rough for approx 15 secs before correcting, (not sure if this is due to the water from engine detailing or not) did not experience it as drove a little more

Cruise control inoperative **

Logbook records stop at around 160,000km. and missing the first 80,000km

blowing a little bit of black smoke upon acceleration which could be normal for a lot of diesel engines around these kilometres.



Ratings & Additional Comments



OVERALL RATING

GOOD FAIR POOR



ADDITIONAL COMMENTS

*I confirm I have inspected, and road tested the
above vehicle as per the findings of this report*

Name: W - Rony Andraos

Date: 4/7/2025


ABN: 12 676 615 991

Mobile: 0481253589

Photos



INTERIOR



EXTERIOR



Photos



ENGINE BAY



TYRES, WHEELS & BRAKES





Photos



ROAD TEST

SCHEDULED MAINTENANCE SERVICE HISTORY

Scheduled Maintenance Service	Intermediate Service (Optional)
132 Months / 155,000km (whichever occurs first)	138 Months / 172,500km (whichever occurs first)
Date of Service: 2/12/21	Date of Service:
Repair Order No: 167 790	Repair Order No:
Kilometres:	Kilometres:
Dealer's Signature: [Signature]	Dealer's Signature:
Print Name: Michael	Print Name:
Tick Box To Confirm:	Tick Box To Confirm:
<input type="checkbox"/> Checked for Outstanding Recalls and Service Campaigns	<input type="checkbox"/> Checked for Outstanding Recalls and
<input type="checkbox"/> System Hyundai Global Diagnostic System (GDS) Check	
Optional Intermediate Maintenance is in operating in accordance with the contract	
SERVICING VALIDATION STAMP	

G FORCE
Automotive Services Pty Ltd
Unit 11 Maxwell Place
NARELLAN NSW 2567
Ph: 4646 1400 / MVR: 53969

Service, front rotors, N/S stop light



Disclaimer



- It is the responsibility of the buyer to check for any financial interest owing on the vehicle and for any write off or stolen vehicle before purchasing the vehicle
- The Pink Slip Today inspection is not a guarantee or warranty and is valid only at the time of inspection
- Is the responsibility of the buyer to conduct a visual inspection of the vehicle at the final point of sale as Auto King can only advise on the condition of the vehicle at the time of inspection
- Advice on the vehicle inspected is provided in context of the age and condition of the vehicle at the time inspected
- The purchaser must take responsibility for the authenticity of the vehicle. VIN & Engine numbers are recorded by our inspectors however authenticity cannot be guaranteed
- The Pink Slip Today inspection is VISUAL only. No removal of parts or components is undertaken during the inspection process
- If there is a dispute about the content of this report, the purchaser must refer the vehicle back to Pink Slip Today prior to proceeding with any repairs
- This report serves to identify any visually detected problems however dismantling components may be subsequently required so as to provide a more accurate diagnosis
- The inspection report is prepared for the person named on the report and not for use by any third party.

PINK SLIP TODAY DOES NOT CHECK THE FOLLOWING ITEMS

- Timing belts
- Fuel & Oil consumption
- Trip meters / Computers
- Alarm / Security system
- Navigation equipment / GPS
- Operation of TV, cassette, CD or IPOD connection
- Automatic switching of wipers and lights
- Compression of engine
- Anti-locking braking system (ABS)